

FIG 1a

↓
FLIP
↓




FIG 1b

↓
GRIND
↓




FIG 1c

↓
ETCH AND POLISH
↓




FIG 1d




FIG 1e

↓
LASER CUT
↓




FIG 1f

28 →




FIG 1g




FIG 2a

FLIP




FIG 2b




FIG 2c




FIG 2d

SILICON BOND




FIG 2e

ETCH




FIG 2f

FLIP




FIG 2g

SHEAR




FIG 2h

ETCH AND POLISH




FIG 3a

FLIP




FIG 3b




FIG 3c






FIG 3d

SILICON BOND



FLIP



SHEAR




FIG 3g

ETCH AND POLISH




FIG 3h




FIG 3i




FIG 3j